
7. The water environment


Figure 7.1 Surface water features and catchments


Figure 7.2 Groundwater feature


Figure 7.3 Fluvial flooding

Figure 7.4 Surface water flooding











8. Landscape and visual

Figure 8.1 Landscape and visual




9. Geology and soils

Figure 9.1 Agricultural classifications



10. Cultural heritage


Figure 10.1 Historic environment




11. Materials and waste

Figure 11.1 Mineral safeguarding areas within project area


Figure 11.2 Mineral safeguarding areas within Wiltshire





12. Population and health

Figure 12.1 Farms



Path: P:\ADST\Deliver Work\IUTO\Geospatial\5197936_A350MelkshamBypass\006_TaskRegister\GT00066_EIAMapping\WIP\5197936_FIG12-1_00.mxd

3rd Floor, County Gate, County Way, Trowbridge BA14 7FJ